mini-GUIDE

## SET UP THE PASCO WEATHER SENSOR WITH SPARKvue

STEP 1:

To Turn on the Sensor: press the ON/OFF button.

- All three status LEDs will shine for a short time.
- If the battery is charged, the Battery status LED will stop shining.
- The GPS status and the Bluetooth status LEDs will continue to blink. This indicates that the device is now ready to connect.

To turn **off** the sensor, press and HOLD the ON/OFF button until the Battery status LED shines red momentarily and the other status LEDs stop shining.

STEP 2:

To connect the sensor wirelessly with SPARKvue software, start the SPARKvue data collection software on your laptop, Chromebook or tablet, and click the 'Sensor Data' icon.

[To use the weather sensor to gather data remotely, while not connected to a laptop or other device, click the 'Remote Logging' icon.]

Information 👁 👁 At A Glance

STEP 3:

**To Open the Wireless Sensor's Window:**

In the Home screen, select the "Bluetooth" icon at the top of the screen. The Wireless Sensor's window opens – select the sensor that has **the same 6-digit number** as on the front of the weather sensor.

SPARKvue Wireless Devices Window

STEP 4:

To Start a New Experiment Using the Pasco Weather Sensor

To begin a new experiment in which you will use the Pasco Weather Sensor to take measurements of one or more types of weather-related data, click the 'Build New Experiment' button.[1]

---

[1] All content comes from https://www.pasco.com/products/sensors/environmental/ps-3209
https://www.pasco.com/products/software/sparkvue

Information 👁 👁 At A Glance